

Quality Low-Hydrogen Electrode with Welds of X-Ray Integrity

EutecTrode® 66N



WELDING

- Superior arc stability with virtually spatter-free metal transfer
- “N” formulation enables all diameters to be operated at lower amperage levels
- Deposits have moderately heavy slag, which is extremely easy to remove



DESCRIPTION:

EutecTrode 66N is an all-position electrode with excellent bead control, crack resistance and mechanical properties.

66N is suitable for most carbon and low-alloy steels, including use as a scavenger of “tramp” elements in the welding of high sulfur or phosphorous bearing steels.

TYPICAL APPLICATIONS:

- General boiler welding
- Ship hull construction
- Pressure vessels and connections
- Heavy-duty equipment
- Metal-production fabrication

TECHNICAL DATA:

Recommended Polarity: DCEP (+) or AC (~)
Typical Tensile Strength: 85,500 psi
Typical Yield Strength: 73,200 psi
Typical Elongation (1=5d) min.: 22%

Availability and Recommended Amperages

A: Thick Sections, Heavy Build-Up (Multi-Pass)				
Diameter	3/32" (2.4mm)	1/8" (3.2mm)	5/32" (4.0mm)	3/16" (5.0mm)
Amperage	75-100	120-160	170-200	230-275
B: Thin Sections, Out-Of-Position				
Diameter	3/32" (2.4mm)	1/8" (3.2mm)	5/32" (4.0mm)	3/16" (5.0mm)
Amperage	55-70	100-120	140-175	NA

WELDING PARAMETERS:

Preparation: Clean all weld surfaces, paying particular attention to removing grease, oil and rust. Prepare joints mechanically or use Xuper®ExoTrode® surface preparation electrodes to scarf open a nominal 60° “V”. Lightly grind or brush surfaces to remove slag, oxides and debris which might contaminate the weld.

Preheat and Interpass Temperatures: Temperature ranges are determined from both the carbon and alloy content of the base metal. For some low alloy, high-tensile steels, a preheat of 500° F (260° C) is recommended.

Welding: Maintain a short to medium arc length and avoid contact welding. Deposit stringer beads of no more than two times the electrode diameter. Back-whip all craters.

Use of Run-off tabs is highly recommended to avoid stop-start porosity and embrittlement, especially on hardenable steels.

YOUR RESOURCE FOR PROTECTION, REPAIR AND JOINING SOLUTIONS



Eutectic Corporation
N94 W14355 Garwin Mace Drive
Menomonee Falls, WI 53051 USA
P 800-558-8524 • F 262-255-5542
www.eutecticusa.com

Eutectic Canada
428, rue Aime Vincent
Vaudreuil-Dorion, Quebec J7V 5V5
Phone: (800) 361-9439
Fax: (514) 695-8793
www.eutectic-na.com

Eutectic Mexico
KM 36.5 Autopista
Mexico-Quertaro
54730 Cautitlan-Izcalli
Estado de Mexico, Mexico
Phone: 011 (52) 55-5872-1111
e-mail: eutectic@eutectic.com.mx